SPECIFICATION SHEET

E71T-11 Flux Cored Gasless Wire





Features: -

A smooth running gasless wire with minimal spatter for general welding

Suitable for single or multipass welds

For use with portable welders, no gas required. Ideal for use outside and/or in windy conditions.

DC EN - DC current, electrode negative polarity.

Foil sealed packaging for long shelf life

Recommended Gases: -

n/a

Classifications: -

ISO 17632 / BT 49 Z T14 1 SN A

AS/NZS 17632

AWS A5:20 E71T-11

E71T-11

Recommended Settings

Wire Size	Position	Current Range	Voltage Range
0.8	Horizontal	60-100	18-20
0.8	Vertical & O/Head	50-100	18-20
0.9	Horizontal	70-120	18-20
0.9	Vertical & O/Head	60-100	18-20

Typical Me Properties		Welding Grade			
Yield Stres	SS	480 MPa			
Tensile St	rength	550 MPa			
Elongation	1	21.5%			
Typical Chemical Composition (%): -					
С	0.18	Ti + Zr			

Typical Chemical Composition (%): -					
С	0.18	Ti + Zr			
Si	0.46	Cr			
Mn	0.32	Мо			
Р	0.014	V			
S	0.007	Cu			
Ni		Al	1.05		
Test certificate is available per batch of wire.					

Suitable for all positional welding



Available Sizes: -					
Item	Desc	Dia	Spool		
111574	ME71T110809	0.8mm	0.9kg 100D		
111575	ME71T110845	0.8mm	4.5kg 200D		
111576	ME71T110909	0.9mm	0.9kg 100D		
111577	ME71T110945	0.9mm	4.5kg 200D		

WARNING

Protect yourself and others. Read and understand this information. FUMES and GASES can be dangerous to your health. ARC RAYS can injure eyes and burn skin. Always wear correct personal protective equipment (PPE). Avoid inhalation of fumes. Assure there is addeuate natural or exhaust ventilation at the point of welding/source of fumes. Never touch live electrical parts. ELECTRIC SHOCK CAN KILL. Before use, read and understand the relevant Material Saftey Data Sheets (MSDS) or Safety Data Sheets (SDS) and your employers safety regulations and polices. For additional information regarding safety issues please refer to AS1674 and WTIA technical note TN07. Caution: be sure package is dry upon receipt. Store in a dry area above 10°C. First Aid - if exposed to excess welding fumes, remove to fresh air, in case of arc rays or electric shock employ normal first aid techniques and call a physician immediately.

DO NOT COVER OR REMOVE THIS INFORMATION AND WARNING